





Cone bolt manufactured by cold - forming:



Cone bolt manufactured by turning:



- ① Expansion sleeve
- ② Cone bolt (cold – formed or turned)
- ③ Washer
- ④ Hexagon nut
- ⑤ BTI BAZ dome nut



(Fig. not to scaled)

BTI Simplexanchor BAZ, BAZ A4, BAZ C

Product description
Installed condition

Annex A 1